



VOLVO V60: 1EMA927

Vinnnumber:	YV1FW31A1D1121864	Versionname:	V60 D3 Kinetic St/St
First Registrationdate:	18/01/2013	Fiscalpower:	136PK
Expertise Mileage:	142317	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1512
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/45/17/97 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	190,00
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

