



MERCEDES C: 1EFH301			
Vinnnumber:	WDD2042001G042673	Versionname:	C BRE 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	15/11/2012	Fiscalpower:	
Expertise Mileage:	104109	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3322
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
GPS storage HD	Seats electric F R
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting Headlighting Halogen	
Type of GPS GPS big screen color	
Type of Lining Lining fabrics	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes

Total cost ex VAT	1933,46
-------------------	---------


















Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Wheel aperture R L, Scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Door F L, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	349,68
 	
Wing F R, Deformed, Le - Replace and paint	530,02
 	
Bonnet, Repaired, P - Check	0,00
 	
Ignition key, Missing, E - Replace	150,00
	
Wheel aperture R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Wing F L, Bad repair, P - Check	0,00
 	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
 	
Interior, Stain, Cleaning	100,00

