



RENAULT Grand Espace: 1GDP210				
Vinnumber:	VF1JKFHC650148586	Versionname:	GR.ESPACE Business 130PK	
First Registrationdate:	9/01/2014	Fiscalpower:		
Expertise Mileage:	106003	Power Kw:	96	
Bodytype:		Body color	Dark Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	2531	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage		Luggage cover		
GPS storage	SD	Rear parking sensors		
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Sound engine	OK	
Idle position	OK	Clutch test	OK	
Engine startingtime	OK	Wiper fluid level	OK	
Exhaust gass	OK	Lighting	OK	
Transmission	OK	Wiperblades	OK	
Handbrake	OK			
Degree of wear				
	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			1343,72	
Bonnet, Stone chip(s), Acceptable			0,00	
No pictures to display				
Foglight R, Broken, E - Replace			271,64	
Door R L, Bump(s), Acceptable			0,00	
No pictures to display				
Bumper grille F R, Damaged, E - Replace			34,08	



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Interior, Dirty, Cleaning	150,00
---------------------------	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------

