



VOLVO XC60: YP5501			
Vinnnumber:	YV1DZ8256E2544422	Versionname:	XC60 D5 4WD Kinetic Geartr.215PK Aut.
First Registrationdate:	8/12/2015	Fiscalpower:	
Expertise Mileage:	164648	Power Kw:	158
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3810
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	235/65/17/108 H LightMetal			
	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			235,56
Door F L, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Difference in color, Acceptable			0,00



Spoiler R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper moulding R, Scratch(es), Le - Replace and paint	120,00
--	--------

