



BMW 3: 1GDA031

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA3K91040F932075 | Versionname: | 3 TOURING 316d 116PK |
| First Registrationdate: | 6/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 118447 | Power Kw: | 85 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2721 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/92 V LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1379,85 |
|-------------------|----------------|




| | |
|---|---------------|
| Door R L, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|---------------|



| | |
|---|--------------|
| Wing R R, Bump(s), PDR - Knock out without painting | 63,00 |
|---|--------------|



| | |
|---------------------------------|-------------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
|---------------------------------|-------------|

| | |
|--|--------|
| <i>No pictures to display</i> | |
| Ignition key, Missing, E - Replace | 150,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|  | |
| Door F R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|  | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|  | |