


BMW 1: 1HSX044

Vinnumber:	WBA1C91070P695807	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	24/09/2014	Fiscalpower:	
Expertise Mileage:	151432	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3306
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/55/16/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	813,60
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rearview mirror housing L, Missing, E - Replace 150,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00

