



BMW 3: 1FH0836

Vinnumber:	WBA3K91090F931245	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	185426	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	469,80
Foglight L, Broken, E - Replace	138,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Towhook (removable), Incomplete, E - Replace	25,00
--	-------



Boot carpet, Stain, Acceptable	0,00
--------------------------------	------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Wing R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display