


BMW 3 BERLINE: 1KEB369

Vinnumber:	WBA3D110X0F396860	Versionname:	2.0 318D (105KW) BERLINE
First Registrationdate:	13/04/2015	Fiscalpower:	
Expertise Mileage:	136846	Power Kw:	105
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

205/60/16/96 H Steel				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	711,55
-------------------	---------------

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display


Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F L, Scratch(es), E - Replace 30,00



Interior, Dirty, Cleaning 25,00

