



MERCEDES B: 1DWP513			
Vinnnumber:	WDD2462001J103565	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	19/09/2012	Fiscalpower:	
Expertise Mileage:	120277	Power Kw:	80
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3105
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	HD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/45/17/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 4 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	1386,58
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08

Wing R L, Bump(s), LI - Repair and paint (complete)	308,20

Front bumper, Scratch(es), Acceptable	0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

