



**BMW 5: 1FID150**

Vinnumber:	<b>WBAFW91070DW48680</b>	Versionname:	<b>5 BER 520d</b>
First Registrationdate:	<b>4/07/2013</b>	Fiscalpower:	<b>Eff.Dyn.Ed.St/Stp 163PK</b>
Expertise Mileage:	<b>111553</b>	Power Kw:	<b>120</b>
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3209</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>380,00</b>
-------------------	---------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

