


**CITROEN GRAND C4 Picasso: 1FKT743**

Vinnumber:	<b>VF7UA9HR8DJ681344</b>	Versionname:	<b>HDI</b>
First Registrationdate:	<b>31/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>86542</b>	Power Kw:	<b>82</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>5/10/2017</b>	Parking lot:	<b>3610</b>
Maintenance	<b>OK</b>		
Maintenance	<b>81200</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 958,24

**Ignition key, Damaged, P - Check** 0,00

**Wing R L, Bump(s) and scratch(es), It - Spot repair** 139,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00



Floor covering F L, Worn, P - Check

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Internal Boot Lining R, Scratch(es), Acceptable

0,00



Boot carpet, Damaged, Smart repair

64,32



Wing F R, Scratch(es), Acceptable

0,00

Wing F R, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00



Dashboard, Scratch(es), Acceptable 0,00



Interior, Stain, Chemical cleaning 150,00



Interior, No damage, P - Check 0,00



Door R L, Scratch(es), Acceptable 0,00



Wing F L, Bump(s), PDR - Knock out without painting 63,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00



Door F R, Bump(s) and scratch(es), It - Spot repair 139,56

