


 8179.5  
 for  
 70483

**MERCEDES A: 1HLK872**

Vinnnumber:	<b>WDD1760121V022730</b>	Versionname:	<b>A 180CDI BE Edition 109PK</b>
First Registrationdate:	<b>20/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>70483</b>	Power Kw:	<b>80</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2627</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**


	<b>195/65/15/81 T Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 9 mm</b>	Fr.R.	<b>Uniroyal: 9 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

 Total cost ex VAT 271,80

 Wheel cover R L, Scratch(es), Acceptable 0,00
*No pictures to display*

 Wheel cover R R, Damaged, E - Replace 30,00

 Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

 Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00

