


FORD Focus: 1EJR569

Vinnnumber:	WF0LXXGCBCT24642	Versionname:	FOCUS CLIP. ECONetic Trend 88g 105PK
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	152779	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	VS		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 MS Steel			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	187,32
Door F L, Bump(s), PDR - Knock out without painting	63,00



Wing R L, Bump(s), Acceptable	0,00
-------------------------------	-------------



No pictures to display


Wing R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
	
Wheel cover R L, Missing, E - Replace	30,00
	
Wheel cover F L, Scratch(es), Acceptable	0,00
No pictures to display	
Backrest cover F L, Hole, Smart repair	64,32

	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Stone chip(s), Acceptable	0,00
No pictures to display	