



**FORD Mondeo: 1GBC329**

Vinnnumber:	<b>WFOEXXGBBEDG03068</b>	Versionname:	<b>MONDEO BER Econetic Titanium Style 115PK</b>
First Registrationdate:	<b>12/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>104400</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2230</b>
Maintenance	<b>LAATSTE ONDERHOUP 101595KM 12 2017</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/50/17/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 6 mm</b>	Fr.R.	<b>Fulda: 7 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>919,50</b>
--------------------------	---------------

<b>Bumper trim R, Broken, E - Replace</b>	<b>113,94</b>
---	---------------



<b>Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Outer door handle R L, Scratch(es), Paint 75,00



Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Roof, Bump(s), Acceptable 0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Interior, Worn, Acceptable 0,00

*No pictures to display*