



FORD C-MAX: 1CAF523

Vinnnumber:	WFOJXXWPBJBJ57662	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	4/10/2011	Fiscalpower:	
Expertise Mileage:	90611	Power Kw:	70
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2428
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1385,18
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F R, Bad repair, Paint	0,00
-----------------------------	------



Wing F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

