



**PEUGEOT 508: DT4844**

Vinnumber:	<b>VF38URHC8DL042631</b>	Versionname:	<b>508 SW RXH BMP STT 163PK Aut.</b>
First Registrationdate:	<b>13/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>135114</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3622</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	<b>Headlighting Xenon</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>245/45/18/100 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 7 mm</b>	Fr.R.	<b>Michelin: 7 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Total cost ex VAT	591,80
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------





Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

*No pictures to display*

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------

