



NISSAN Qashqai: 1HPS751			
Vinnumber:	SJNFAAJ11U1144376	Versionname:	QASHQAI 2WD Connect Ed.110PK
First Registrationdate:	8/09/2014	Fiscalpower:	
Expertise Mileage:	157639	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2532
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/60/17/96 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1354,98
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20

Wing F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Dirty, Cleaning		25,00



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

