



MERCEDES A: 1HJK384

Vinnumber:	WDD1760121V020541	Versionname:	A 180CDI BE Edition 109PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	108300	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1311
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 V LightMetal			
Winter tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Firestone: 8 mm	Re.R.	Firestone: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 271,80

Bumper R, Bad repair, Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Front bumper, Bump(s), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Headlight R, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display