



RENAULT Clio: 1EWE855			
Vinnumber:	VF15RJL0H48730170	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	5/04/2013	Fiscalpower:	
Expertise Mileage:	127919	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3829
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Repair kit	Yes Compressor Yes


Total cost ex VAT	2368,42
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Broken, Le - Replace and paint	535,20



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Waterinfiltration, Cleaning 75,00



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Not original part, E - Replace 24,00



Wheel cover F R, Not original part, E - Replace 24,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Bump(s), LI - Repair and paint (complete) 176,14



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,06



Wheel cover R R, Not original part, E - Replace 24,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Seat cover F L, Damaged, Acceptable 0,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F L, Not original part, E - Replace 24,00




Windscreen, Scratch(es), E - Replace 413,76



Electricity circuit, Not functioning (well), Diagnosis 0,00



Floor covering F L, Tear, E - Replace 240,00



Roof pillar L, Bump(s) and scratch(es), LI - Repair and paint (complete) 176,14



Roof, Bump(s), Acceptable 0,00

No pictures to display

Gear shift lever knob, Damaged, Acceptable 0,00

No pictures to display