



OPEL VIVARO: 1NHJ607

Vinnnumber:	WOL3F701EGV626371	Versionname:	
First Registrationdate:	3/02/2016	Fiscalpower:	
Expertise Mileage:	81746	Power Kw:	86
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1619
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	395,47
-------------------	--------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Seat cover F R, Hole, Smart repair	64,32
------------------------------------	-------



Interior, Dirty, Cleaning	100,00
---------------------------	--------





Trunk door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15

