


RENAULT Grand Scenic: 1ECV275

Vinnumber:	VF1JZ14A648045346	Versionname:	GR.SCENIC Energ.Expression 5Pl.FAP
First Registrationdate:	23/10/2012	Fiscalpower:	110PK
Expertise Mileage:	155678	Power Kw:	81
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	28400 KM	Parking lot	2213
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1345,83

Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display
Rear window, Scratch(es), E - Replace 0,00

Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	366,35
Rocker panel inner R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	283,80
Tailgate, Bump(s), LI - Repair and paint (complete)	421,68
Wheel cover R R, Scratch(es), E - Replace	30,00
Seat cover R, Stain, Cleaning	25,00
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearlight L, Crack, E - Replace	114,00
Wheel cover F R, Scratch(es), E - Replace	30,00
Seat cover F R, Stain, Cleaning	25,00



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover R R, Stain, Cleaning	25,00
---------------------------------	-------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display