



**OPEL Insignia: 1EWR390**

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnumber:              | <b>W0LGT5EM0D1085418</b> | Versionname: | <b>INSIGNIA BER ecofl.Cosmo S/S DPF</b> |
| First Registrationdate: | <b>9/04/2013</b>         | Fiscalpower: | <b>160PK</b>                            |
| Expertise Mileage:      | <b>199647</b>            | Power Kw:    | <b>118</b>                              |
| Bodytype:               |                          | Body color:  | <b>Grey</b>                             |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                          |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2203</b>                             |
| Number of doors:        | <b>4</b>                 |              |   |
| Number of seats:        | <b>5</b>                 |              |   |
| Number head rests:      | <b>5</b>                 |              |   |
| Rims summer:            | <b>Aluminium</b>         |              |   |
| Category:               | <b>Passenger Car</b>     |              |   |
| Oil level:              | <b>OK</b>                |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Front parking sensors        |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                   |                          |       |                          |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
|               | <b>245/45/18/100 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                             | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|               | Re.L.                             | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>211,80</b> |
|--------------------------|---------------|

|  |               |
|--|---------------|
| <b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b> | <b>211,80</b> |
|--|---------------|



|  |             |
|--|-------------|
| <b>Door R L, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

No pictures to display