



OPEL Zafira: TX7721

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WOLPE9EM1D2060359 | Versionname: | ZAFIRA TOURER |
| First Registrationdate: | 14/03/2013 | Fiscalpower: | ecoFL.Cosmo St/St.130PK |
| Expertise Mileage: | 170001 | Power Kw: | 96 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3830 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining semi-leather |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/50/17/8 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 3 mm | Fr.R. | Goodyear: 3 mm |
| | Re.L. | Goodyear: 4 mm | Re.R. | Goodyear: 4 mm |

Assistance equipment

| | |
|--|--------|
| Total cost ex VAT | 527,56 |
| Bumper corner R R, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|-------|
| Bumper Trim F, Scratch(es), E - Replace | 42,00 |
|---|-------|



| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|--------|
| Rear window, Scratch(es), E - Replace | 370,00 |
|---------------------------------------|--------|



Window R R door, Scratch(es), Acceptable 0,00



Window F R door, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display