


NISSAN X-TRAIL: 1SPC257

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | JN1TCAT32U0032623 | Versionname: | |
| First Registrationdate: | 19/06/2017 | Fiscalpower: | |
| Expertise Mileage: | 26454 | Power Kw: | 96 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3404 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | HD | Panoramic roof | |
| GPS storage | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar removable |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/19/99 V LightMetal | | | |
| Summer tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | |
|--|--------|
| Total cost ex VAT | 110,64 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Chemical polution, 67 - Polish | 0,00 |



| | |
|--|--------|
| Bumper trim R, Scratch(es), Smart repair | 110,64 |
|--|--------|



Tailgate, Damaged, Acceptable

0,00

No pictures to display