



SKODA Octavia: 1EGP467			
Vinnnumber:	TMBHT21ZXD2092893	Versionname:	OCTAVIA COMBI GTec Ambition DPF 105PK
First Registrationdate:	27/11/2012	Fiscalpower:	
Expertise Mileage:	149167	Power Kw:	77
Bodytype:	Break	Body color:	Burgundy
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3832
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	195/65/15/91 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2225,76
Bonnet, Scratch(es), LI - Repair and paint (complete)			290,08



Wing R L, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper R, Damaged, LI - Replace and paint		0,00

Bumper R, Damaged, E - Replace and paint 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door trim R L, Scratch(es), E - Replace 114,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

