



**VOLKSWAGEN Crafter 35 LWB HR: 1ELW799**

Vinnumber:	<b>WV1ZZZ2EZD6020771</b>	Versionname:	<b>CRAFTER 35 B/F LWB HR</b>
First Registrationdate:	<b>17/01/2013</b>	Fiscalpower:	<b>143PK</b>
Expertise Mileage:	<b>24248</b>	Power Kw:	<b>105</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV16</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Windows electric F	
Cruise Control	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>235/65/16/115 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 8 mm</b>	Fr.R.	<b>Continental: 8 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	388,76
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76



Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00

---

*No pictures to display*