


RENAULT Grand Scenic: 1FIL780

Vinnumber:	VF1JZNAB649189764	Versionname:	GRAND SCENIC Privil?ge 7pl.130PK
First Registrationdate:	8/07/2013	Fiscalpower:	
Expertise Mileage:	141850	Power Kw:	96
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	8100 KM	Parking lot	3508
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	NOT OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1154,56

Tailgate, Bump(s), Acceptable 0,00

No pictures to display
Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

Rocker panel inner F L, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear roof pillar covering L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Backrest cover R M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Steering wheel, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	163,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 452,20



Backrest cover F L, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Bumper spoiler F, Deformed, E - Replace	42,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Gear shift lever knob, Worn, Acceptable	0,00

<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Boot carpet, Stain, Acceptable 0,00

No pictures to display

Rear roof pillar covering R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ignition key, Not functioning (well), P - Check	0,00
---	------



Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display