



| PEUGEOT 2008: 1GHC942 | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | VF3CU8HR0EY007234 | Versionname: | 2008 Active 68PK |
| First Registrationdate: | 6/02/2014 | Fiscalpower: | |
| Expertise Mileage: | 191277 | Power Kw: | 50 |
| Bodytype: | SUV | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3313 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|-------------------------------|
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|-----------------------------|--------------------------|-------|--------------------------|
| | 195/60/16/89 H Steel | | | |
| Summer tyres: | Fr.L. | Bridgestone: 3 mm | Fr.R. | Bridgestone: 3 mm |
| | Re.L. | Bridgestone: 3 mm | Re.R. | Bridgestone: 3 mm |

| Assistance equipment | | | |
|----------------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |

| | |
|---|---------|
| Total cost ex VAT | 1156,58 |
| Roof, Bump(s), LI - Repair and paint (complete) | 673,50 |





Wheel cover F L, Scratch(es), E - Replace 30,00



Interior, Dirty, Cleaning 100,00



Bonnet, Hail damage, LI - Repair and paint (complete) 290,08



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display