




SEAT Ibiza: 1GUR674			
Vinnumber:	VSSZZZ6JZER124409	Versionname:	IBIZA ST E-Ecom.Style
First Registrationdate:	6/05/2014	Fiscalpower:	75PK
Expertise Mileage:	146129	Power Kw:	55
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3402
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	185/60/15/88 H Steel			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1140,87
Wheel cover F L, Scratch(es), E - Replace			30,00



Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Damaged, Le - Replace and paint	0,00





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00



Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00

