



| | | | |
|---------------------------------|--------------------------|--------------|---------------------------------------|
| MINI Countryman: 1EMJ344 | | | |
| Vinnnumber: | WMWZD11030WL29091 | Versionname: | MINI COUNTRYMAN One D DPF 90PK |
| First Registrationdate: | 22/01/2013 | Fiscalpower: | |
| Expertise Mileage: | 128551 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3431 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Sun Roof electric |
| Windows electric F | Panoramic roof |
| Windows electric R | Luggage cover |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| Winter tyres: | 205/60/16/98 H LightMetal | | | |
| | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

| | |
|--|---------------|
| Assistance equipment | |
| Total cost ex VAT | 665,03 |
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|---------------|
| Bonnet, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|--------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Sill outer R, Scratch(es), It - Spot repair | 115,56 |



| | |
|---|--------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Roof, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Scratch(es), LI - Repair and paint (complete) | 318,35 |

