



RENAULT Grand Scenic: 1FCO203

Vinnnumber:	VF1JZ14M648905081	Versionname:	GR.SCNIC Energ.Bose
First Registrationdate:	24/05/2013	Fiscalpower:	Edit.5pl.FAP 110PK
Expertise Mileage:	179400	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3522
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunction		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/17/95 MS LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Total cost ex VAT	1152,13
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover F L, Damaged, Acceptable 0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Rearlight L, Waterinfiltration, Acceptable	0,00
--	------



Bodywork, No damage, P - Check	0,00
--------------------------------	------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display