



VOLKSWAGEN Golf: 1CQM127			
Vinnumber:	WVWZZZ1KZCW094812	Versionname:	GOLF BER BlueMotion DPF
First Registrationdate:	2/02/2012	Fiscalpower:	105PK
Expertise Mileage:	149244	Power Kw:	77
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	195/65/15/91 T Steel			
	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment	
Compressor	Yes
Total cost ex VAT	84,00
Luggage space cover, Damaged, E - Replace	10,00



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	-------------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>	
Bumper grille, Damaged, E - Replace	74,00

