



VOLKSWAGEN PASSAT: 1GHC299

Vinnumber:	WVWZZZ3CZEE105165	Versionname:	
First Registrationdate:	30/01/2014	Fiscalpower:	
Expertise Mileage:	142738	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3102
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			650,15
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel covers (all), Missing, E - Replace			120,00



Door R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), LI - Repair and paint (complete)			318,35



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
---	--------

