



VOLVO V60: 1EKH275			
Vinnumber:	YV1FW31A1D1124586	Versionname:	V60 D3 Kinetic St/St 136PK
First Registrationdate:	4/01/2013	Fiscalpower:	
Expertise Mileage:	118839	Power Kw:	100
Bodytype:	Break	Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1573,71
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Interior, Dirty, Cleaning	100,00
---------------------------	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Door R R, Bump(s), LI - Repair and paint (complete)

318,35



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56

