



VOLKSWAGEN PASSAT: 1GCP472

Vinnumber:	WVWZZZ3CZEE094157	Versionname:	PASSAT
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	128092	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3120
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Repair kit	Yes		

Total cost ex VAT	1427,95
--------------------------	----------------

Door R L, Bump(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	58,80
---	--------------



Bumper R, Bump(s), LI - Repair and paint (complete)	235,80
--	---------------



Mirror side blinker R, Broken, E - Replace 49,00



Bumper moulding R, Broken, E - Replace 30,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 438,35



Wing R R, Bump(s), LI - Repair and paint (complete) 404,20



Wing F R, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display