



VOLVO V40: 1EHG234

Vinnumber:	YV1MV8481D2022676	Versionname:	V40 D2 Base 115PK
First Registrationdate:	3/12/2012	Fiscalpower:	
Expertise Mileage:	44505	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	33000 KM	Parking lot:	3327
Maintenance	25/01/2017		
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	95,00
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Seat cover F L, Stain, Acceptable	0,00
No pictures to display	
Maintenance, Maintenance, Execute	0,00



Headlight R, Waterinfiltration, P - Check	0,00
---	------



Seat cover R R, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Headlight L, Waterinfiltration, P - Check	0,00
---	------

