



VOLVO V40: 1FTK667

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnnumber: | YV1MV8481E2099550 | Versionname: | 1.6D |
| First Registrationdate: | 18/10/2013 | Fiscalpower: | |
| Expertise Mileage: | 76847 | Power Kw: | 84 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | IN 5609 KM | Parking lot: | 2609 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | DVD |
| Windows electric F | Rear parking sensors |
| Windows electric R | Type of Tow bar |
| Cruise Control | Tow bar removable |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Adaptive cruise control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | | |
|--------------------|------------|------|------------|
| Spare tyre compact | Yes | Jack | Yes |
|--------------------|------------|------|------------|

Total cost ex VAT 0,00

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bad repair, P - Check 0,00





| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F L, Stain, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Mirror side blinker L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |