



VOLKSWAGEN Touran: 1GAA478

Vinnnumber:	WVGZZ1TZEW049148	Versionname:	TOURAN Highline BMT St/St DSG 105PK Aut.
First Registrationdate:	3/12/2013	Fiscalpower:	
Expertise Mileage:	76711	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3328
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/94 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1884,21
-------------------	----------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	349,68
---	---------------





Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 235,80



Rearview mirror L complete, Unclamped, N - Fit/Remove 24,00



Bonnet, Bump(s), LI - Repair and paint (complete) 434,08



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Bump(s), LI - Repair and paint (complete) 310,50



Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	