


**OPEL Zafira: 1GAZ195**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WOLPE9E34E2034508</b> | Versionname: | <b>ZAFIRA TOURER<br/>ecoFL.Cosmo S/S 136PK</b> |
| First Registrationdate:            | <b>11/12/2013</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>106329</b>            | Power Kw:    | <b>100</b>                                     |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                 |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2511</b>                                    |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                      |  |
|--------------------------------|------------------------------|----------------------|--|
| Radio CD                       |                              | Central consol F     |  |
| Windows electric F             |                              | Luggage cover        |  |
| Windows electric R             |                              | Rear parking sensors |  |
| Cruise Control                 |                              |                      |  |
| Steering wheel multifunctional |                              |                      |  |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |  |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |  |
| Type of Lining                 | <b>Lining semi-leather</b>   |                      |  |
| Type of climate control        | <b>Autom climate control</b> |                      |  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/16/95 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|   |        |
|---|--------|
| Total cost ex VAT                           | 215,88 |
| Inner door handle R L, Damaged, E - Replace | 36,00  |



|   |        |
|---|--------|
| Bumper R, Scratch(es), Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Roof, Chemical polution, Acceptable   | 0,00   |
| <i>No pictures to display</i>   |        |
| Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 115,56 |



Floor covering F L, Hole, Smart repair

64,32

