



| VOLVO V60: 1GQF692 | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | YV1FW8481E1203356 | Versionname: | V60 BRE D2 Kinetic 115PK |
| First Registrationdate: | 1/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 132518 | Power Kw: | 84 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2229 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Seats electric F L |
| Windows electric F | Central consol F |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres: | 225/45/17/97 V LightMetal | | | |
| | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

| Assistance equipment | |
|----------------------|------------|
| Repair kit | Yes |
| Compressor | Yes |

| | |
|---|---------------|
| Total cost ex VAT | 440,00 |
| Luggage space cover, Missing, E - Replace | 240,00 |



| | |
|--|---------------|
| Trunk lid covering R, Dirty, Chemical cleaning | 150,00 |
|--|---------------|





| | |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|---------------------------|-------|
| Interior, Dirty, Cleaning | 50,00 |
|---------------------------|-------|



| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display