



VOLKSWAGEN Golf: 1FVU259			
Vinnnumber:	WVWZZZAUZEP534698	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	12/11/2013	Fiscalpower:	
Expertise Mileage:	126070	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3602
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		




Degree of wear				
Winter tyres:	195/65/15/91 H Steel			
	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	511,98
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R, Bump(s), Acceptable	0,00
-----------------------------	------

Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00
	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
	
Interior, Dirty, Cleaning	50,00
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	