



## VOLVO V40: 1FMS290

|                         |                          |              |                  |
|-------------------------|--------------------------|--------------|------------------|
| Vinnnumber:             | <b>YV1MV8481E2094686</b> | Versionname: | <b>DIESEL</b>    |
| First Registrationdate: | <b>21/08/2013</b>        | Fiscalpower: |                  |
| Expertise Mileage:      | <b>42526</b>             | Power Kw:    | <b>84</b>        |
| Bodytype:               |                          | Body color:  | <b>Blue</b>      |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3527</b>      |
| Number of doors:        | <b>5</b>                 |              |                  |
| Number of seats:        | <b>5</b>                 |              |                  |
| Number head rests:      | <b>5</b>                 |              |                  |
| Rims summer:            | <b>Aluminium</b>         |              |                  |
| Category:               | <b>Passenger Car</b>     |              |                  |
| Oil level:              | <b>OK</b>                |              |                  |

## Options

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                          |
| Windows electric F             |                              | Rear parking sensors |                          |
| Windows electric R             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |
| Level control                  |                              |                      |                          |

## Limited Technical Inspection

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>NOT OK</b> |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>     |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>     |
| Handbrake           | <b>OK</b> |                     |               |

## Degree of wear

|                                  |       |                         |       |                       |
|----------------------------------|-------|-------------------------|-------|-----------------------|
| <b>205/55/16/91 H LightMetal</b> |       |                         |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 5,5 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|                                  | Re.L. | <b>Michelin: 6 mm</b>   | Re.R. | <b>Michelin: 6 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 737,14 |
|-------------------|--------|

|  |       |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|   |        |
|---|--------|
| Front bumper, Scratch(es), It - Spot repair | 115,56 |
|---|--------|



Spoiler R, Scratch(es), 67 - Polish

55,19



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), 67 - Polish

55,19



Rear bulkhead lining, Scratch(es), Smart repair

110,64



Door F L, Scratch(es), It - Spot repair

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

