



VOLKSWAGEN Sharan: 1EKN200			
Vinnumber:	<b>WVWZZZ7NZDVO20860</b>	Versionname:	<b>SHARAN Comfortline BMT</b>
First Registrationdate:	<b>7/01/2013</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>116087</b>	Power Kw:	<b>100</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>BF Goodrich: 5 mm</b>	Fr.R.	<b>BF Goodrich: 5 mm</b>
	Re.L.	<b>BF Goodrich: 6 mm</b>	Re.R.	<b>BF Goodrich: 6 mm</b>

Assistance equipment	
Total cost ex VAT	323,16
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Protection plate M, Strained , E - Replace	69,00
--	-------



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*