



**TOYOTA Verso: PW5797**

Vinnnumber:	<b>NMTDD26R40R094872</b>	Versionname:	<b>VERSO Comfort 5pl. 126PK</b>
First Registrationdate:	<b>6/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>117221</b>	Power Kw:	<b>91</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3502</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>1705,80</b>
-------------------	----------------

Wing F L, Bump(s), LI - Repair and paint (complete)	<b>220,18</b>
-----------------------------------------------------	---------------










Door trim R L, Damaged, E - Replace	<b>114,00</b>
-------------------------------------	---------------



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

No pictures to display

Door trim R R, Damaged, E - Replace	114,00
	
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
	
Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Rear bulkhead lining, Damaged, Smart repair	110,64
	
Sill outer L, Scratch(es), LI - Repair and paint (complete)	310,50
	
Door trim F R, Damaged, E - Replace	114,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door trim F L, Damaged, E - Replace	114,00
