


TOYOTA Verso S: 1DLK517

Vinnnumber:	JTDKC3C3X01004185	Versionname:	VERSO S Luna DPF 90PK
First Registrationdate:	15/06/2012	Fiscalpower:	
Expertise Mileage:	178149	Power Kw:	66
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3405
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
Windows electric F	Luggage cover
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	185/65/15/88 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	923,44
Seat cover F R, Stain, Forfeit	12,00



Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Rearview mirror glass L, Damaged, E - Replace 18,00



Bumper Trim F, Damaged, E - Replace 42,00



Seat cover F L, Stain, Forfeit 12,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Rearview mirror R complete, Damaged, E - Replace 168,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 235,80

