




MAZDA CX-5: 1EOJ400			
Vinnnumber:	JMZKEN91600151112	Versionname:	CX-5 4x4 Sport 150PK
First Registrationdate:	6/02/2013	Fiscalpower:	
Expertise Mileage:	140965	Power Kw:	110
Bodytype:	SUV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2719
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/65/17/102 T LightMetal			
Winter tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			374,85
Alloy Rims (all), Not original part, P - Check			0,00



Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	---------------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Bonnet, Bad repair, Paint

0,00

