


BMW 116ed: 1NHS201

Vinnumber:	WBA1C91010J197699	Versionname:	BMW 116ed
First Registrationdate:	14/06/2012	Fiscalpower:	
Expertise Mileage:	166912	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3314
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1397,83
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Maintenance book, Missing, E - Replace			0,00
<i>No pictures to display</i>			
Compressor, Missing, E - Replace			210,53




Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Wing R R, Scratch(es), 67 - Polish 55,19



Shutter / cover, Scratch(es), E - Replace 150,00



Bonnet, Rust, LI - Repair and paint (complete) 290,08



Tyre repair kit, Missing, E - Replace 210,53

