


AUDI A3: 1GDZ324

Vinnnumber:	WAUZZ8V2EA118907	Versionname:	A3 SB Ambiente 105PK
First Registrationdate:	13/01/2014	Fiscalpower:	
Expertise Mileage:	153254	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4204
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	864,60
-------------------	--------

Roof, Bump(s), PDR - Knock out without painting	82,80
---	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Bad repair, P - Check	0,00
---------------------------------	------



Door R L, Bad repair, P - Check	0,00
---------------------------------	------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Crack, E - Replace	487,20
--------------------------------	--------



Door R R, Bump(s), PDR - Knock out without painting	82,80
---	-------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

