



**AUDI A5: 1ELJ966**

Vinnumber:	<b>WAUZZZ8TXDA046884</b>	Versionname:	<b>A5 SB TDie DPF 136PK</b>
First Registrationdate:	<b>14/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>80549</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3507</b>
Maintenance:	<b>9400 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>602,36</b>
Rearlight R , Waterinfiltration, P - Check	<b>0,00</b>



Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 350,16



Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Boot carpet, Stain, Acceptable 0,00

*No pictures to display*

Backrest cover R M, Bump(s), Acceptable 0,00

*No pictures to display*


Wing R R, Bump(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Engine protective plate, Tear, E - Replace 74,40



Wing R L, Bump(s), PDR - Knock out without painting 82,80



Front bumper, Scratch(es), Acceptable 0,00

*No pictures to display*

Backrest cover F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rocker panel inner R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*