


BMW 3: 1GAH806

Vinnumber:	WBA3D11030J625652	Versionname:	3 BER 318d 136PK
First Registrationdate:	5/12/2013	Fiscalpower:	
Expertise Mileage:	169408	Power Kw:	100
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2731
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/96 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1246,24
-------------------	----------------

Sill outer L, Hole, Le - Replace and paint	712,00
--	---------------



Door panel F L, Damaged, Smart repair	110,64
---------------------------------------	---------------




Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

